# Oil Field Environmental Incident Summary

Responsible Party: Iron Horse Trucking LLC

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MERCER 1-13H

Field Name: ELLISVILLE Well File #: 27663

Date Incident: 12/5/2014 Time Incident: 18:30 Facility ID Number:

County: WILLIAMS Twp: 158 Rng: 99 Sec: 13 Qtr: NE NW

Location Description: Mercer 1-13H 76th & 128th

Submitted By: Kelly Martinez Received By:

Contact Person: Val Jolley

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 30 Barrels 25 Barrels 30 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 9/29/2016 Clean Up Concluded: 12/15/2014

**Risk Evaluation:**Environmental hazard

Areal Extent:

## Potential Environmental Impacts:

Contaminated soil on location, no further impacts.

## Action Taken or Planned:

Spill was cleaned up immediately by SPYDR Oilfield Services. A back hoe was used and approximaetly 9" - 12" removed and hauled to Indian Hills Disposal. Ground was frozen so spilled production water did not penetrate the ground.

Wastes Disposal Location: Indian Hills Solid Waste Disposal

Agencies Involved: Williams County Emergency Disaster - Ed (701) 570-6846

ND Department of Health - Kris Roberts (701) 391-0982

# **Updates**

Date: 12/9/2014 Status: Inspection Author: Kangas, Kathleen

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

NDDoH inspector spoke to on-site roustabout personnel. The well pad area has been cleaned. Indications are that brine also may have leaked on to roadway between the well site and the salt water disposal site. Three samples were taken from the roadway at the intersection of 76th and 128th.

Date: 4/11/2016 Status: Inspection Author: Suess, Bill

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Visited the site at 16:00 on 4/7/2016 and found no visible signs of impacts. All areas between the well pad and the roadway show healthy vegetation. No further action is warranted.

Date: 6/6/2016 Status: Correspondence Author: Suess, Bill

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.